

Inquiry Num 12041

<http://www.pro-electr.net>

Inquiry Date 2017/12/13 0:00:00

Address Info

Name : Skobenko Maksim

Clerk:Susan

Phone Number:0661847131

Email:max_subaru@mail.ru

Address Detail:Krasnova 7a /140

Ukraine,Zaporozhie

Product(s)

Product	Package	TargetPrice	Quantity	SubTotal
IRGPS4067D <i>TRANS IGBT CHIP N-CH 600V 240A 3-PIN(3+TAB) SUPER-247 TUBE</i>	INTERNATIONAL RECTIFIER	\$1.7000	10	\$17.0000
HGTG20N60A4D <i>Trans IGBT Chip N-CH 600V 70A 290000mW 3-Pin(3+Tab) TO-247 Tube</i>	FAIRCHILD/ON	\$0.8600	10	\$8.6000
HGTG12N60A4D <i>Trans IGBT Chip N-CH 600V 54A 167000mW 3-Pin(3+Tab) TO-247 Tube</i>	FAIRCHILD/ON	\$0.8600	20	\$17.2000
IRG4PF50WDPBF <i>Trans IGBT Chip N-CH 900V 51A 200000mW 3-Pin(3+Tab) TO-247AC Tube</i>	IR/Infineon	\$2.0300	10	\$20.3000
IRFP450 <i>TRANS MOSFET N-CH 500V 14A 3-PIN(3+TAB) TO-247</i>	INTERNATIONAL RECTIFIER	\$0.6500	20	\$13.0000
IRF540 <i>TRANS MOSFET N-CH 100V 28A 3-PIN(3+TAB) TO-220AB</i>	INTERNATIONAL RECTIFIER	\$0.5000	20	\$10.0000
IRF9540N <i>Trans MOSFET P-CH Si 100V 23A 3-Pin(3+Tab) TO-220AB Tube</i>	INTERNATIONAL RECTIFIER	\$0.4200	20	\$8.4000
PC817 SOP4 <i>SOP4</i>	SHARP MICROELECTRONICS OF THE AMERICAS	\$0.0600	100	\$6.0000
P6KE24CA <i>DIODE TVS SINGLE BI-DIR 20.5V 600W 2-PIN DO-15 T/R</i>	VISHAY SEMICONDUCTORS	\$0.0200	100	\$2.0000
74HC14S14 <i>Inverter Schmitt Trigger 6-Element CMOS 14-Pin SO T/R</i>	DIODES INCORPORATED	\$0.1500	100	\$15.0000

Sub-Total \$117.5000

Order Total \$117.5000

All payments are paid by customers

1. We are promising 60 days quality assurance for the goods(NEW AND NOT USED)quality assurance from the day you received the goods,and If more than 60 days,we refuse to return.
- 2.Any quality problem with the parts,please send the test report on us and then ships back the same goods we are supplied to you. when we got the goods,we will refund the payment to you

If returning parts heppend in 60 days,parts should be the same as we shipped you.And you should send us the testing report,if it can be passed,when we receive the parts,we will return you the payment.If the parts are damaged on stained with tin will be refused to be returned.